


1706 C/S Rreq Brake lines Rubbing






1706 rust on rear frame crossbar





1706- S/S center wheel speed sensor/ABS lines rubbing frame





1706 - SLS Battery Box Middle Use Electrical Tape to Cover Exposed High Voltage Line






1706 - rear by Euro Filter Roof cracking






1706 - all passenger door sensitive Edge lines rubbing





1706 S/S in front of joint Trim not sealed and/or separating






1706 S/S in front of joint starting to separate





1706 - Coolant reservoirs Empty





1706 - Gusset






1706 - center cross over plate rusting





1706 c/s rear Heater hoses rubbing





1706 C/S Bridge plate Center door incomplete weld





1706 in Front of bellows






1706 - C/S Weld on Bridge Plate area rusting weld






1706 - Front lines Hanging down + not supported





1706 - S/S Front Roof Panels Cracking






1706 - S/S in Front of Joint Trim Falling off + Separating on Rxt areas





1706 - C/S rear of joint roof, Coloumn & Frame starting to separate






1706 - S/S Engine Compartment High voltage lines ribbunny





1706-C/S High voltage line and Fire Suppression line rubbing on Frame





1706 Gusset Rusty





1706 - rust on rear Frame Cross over

