A close-up photograph of a metal structure, likely an aircraft fuselage, showing a crack in a panel seam. The crack is a thin, dark line running along the edge of a white-painted metal panel. The surrounding metal is polished and reflective. A cylindrical metal component, possibly a rivet or a fastener, is visible on the right side of the frame. The lighting is bright, highlighting the texture of the metal and the sharpness of the crack.

1709 cracked panel seem


1709 Rusted weld



1709 Rusted weld and unfinished




1709 weld unfinished






1709 high Voltage Lines rubbing

A close-up photograph of a metal panel seam. The panel is light-colored and appears to be part of a larger structure. A crack is visible along the seam. To the right, a vertical metal rod or pipe is visible, secured with a nut and washer. The lighting is bright, highlighting the metallic surfaces and the crack.

1709 Crack on panel seem


1709 Misaligned Window




1709 high Voltage Lines rubbing




1709 high Voltage Line
sealed w/ electrical tape





1709 high Voltage Line
sealed w/ electrical
tape

A close-up photograph of a metal assembly, likely a part of a vehicle's chassis or suspension. The assembly consists of several metal components, including a horizontal bar and a vertical rod. A prominent feature is a weld joint that is rusted and unfinished, with a yellowish-brown residue visible. The background is a dark, textured surface, possibly a metal plate with a circular pattern. The foreground shows a brick wall.

1709 Rusted and unfinished weld

A close-up photograph of a metal weld joint on a dark, possibly black-painted, structure. The weld is heavily corroded, showing a bright orange-brown rust. The surrounding metal surface is dark and appears to have some surface texture or peeling paint. The background is out of focus, showing a wooden wall and a window with a mesh screen. A red text overlay is positioned in the lower-left quadrant of the image.

1709 Rusted weld

1709 poor finish



1709 poor finish