



1710


1710 Questionable welds, rust, and incomplete




1710 Bridge plate weld poor and incomplete



1710 brake chamber air




1710 Lines are rubbing



The image shows a close-up of industrial machinery. In the foreground, a black hose with yellow labeling is visible. The yellow text on the hose reads "minotuff" with a logo, "1/2\" WP 16.0 MPa (2320 PC", and "20 16 1". In the background, several orange corrugated hoses are bundled together and secured with a black strap and a red buckle. The hoses are surrounded by various metal components, including pipes and bolts.


1710 Lines are rubbing




1710 High voltage line terminal is only insulated with electrical tape




1710 Fire suppression line is rubbing
High voltage cable is loose in clamp



1710 High voltage cable
rubbing



1710 High voltage cable
rubbing




1710 High voltage cable
is smashed



1710 High voltage cables
rubbing



1710 High voltage cable
rubbing



1710 Sensitive edge line
rubbing



1710 Front of joint,
warped panel



1710 Cracking panel

