



1713




1713 Front of joint, warped panel




1713 Sensitive edge line rubbing




1713 High voltage cable
rubbing




1713 High voltage cable
is smashed



1713 High voltage cable is smashed




1713 Cracked weld




1713 Cracked weld




1713 Lines are rubbing



1713 Lines are rubbing






1713 Lines are rubbing

1713 High voltage line terminal is only insulated with electrical tape



1713 High voltage cable rubbing




1713 High voltage cable rubbing


K11M-2105920D HVDB-4
12063066-00 A/0
BYD AUTO BYD 比亚迪汽车
K11M-2105920D HVDB-4

K11M-2105340C HVDB-8
Integrated Controller Steering Hv Wiring Harness Assembly
01046WSCH61000016
01046WS716100016

1713 Jack point is questionable



1713 Bridge plate weld missing



1713 Bridge plate weld missing

