SYSTEM TEST CERTIFICATE



elovate



SYSTEM: DriveSafe
Location Code: 1034

SATISFACTORY.

THIS IS TO CERTIFY THAT ON THE 3RD DAY OF JUNE 2025, SITE **1034** HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE

LOCATION: Lomas at Virginia St - WB

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND TESTIFY THAT THE SYSTEM HAS BEEN INSTALLED CORRECTLY PER THE GUIDANCE OF THE MANUFACTURER AND THAT THE SYSTEM IS IN GOOD WORKING ORDER ON-SITE.

6/3/25

DATE

Mustapha Abdul-Rahim

[name] Technician