





SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 4700 BLK GIBSON BLVD EB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE S<sup>TH</sup> DAY OF APRIL 2024, SITE NMAQFS01 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

4/8/2024 DATED: BY

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 4700 BLK GIBSON BLVD WB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 8<sup>th</sup> DAY OF APRIL 2024, SITE NMAQFS02 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

> 4/8/2024 DATED: BY

Patrick Walters

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 600 BLOCK UNSER AVE NB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 22<sup>ND</sup> DAY OF MARCH, 2024 SITE NMAQFS03 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

\_\_\_\_BY\_\_ Patrick Walters DATED: 03/22/2024

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 2300 BLOCK COAL AVE EB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE S<sup>TH</sup> DAY OF APRIL 2024, SITE NMAQFS04 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 4/8/2024 BY Patrick Walters

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 1900 BLOCK LEAD AVE WB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 9<sup>TH</sup> DAY OF APRIL 2024, SITE NMAQFS05 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

4/9/2024 DATED: BY

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 2500 BLK CENTRAL AVE WB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 6TH DAY OF JULY, 2023 SITE NMAQFS06 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 7/6/2023

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 8400 BLK OF LOMAS BLVD WB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 31ST DAY OF MAY, 2023 SITE NMAQFS07 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 5/31/2023

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: UNSER VIA FLOR DEL SOL PL NB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 31ST DAY OF MAY, 2023 SITE NMAQFS08 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 5/31/2023

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 5000 BLOCK SAN MATEO SB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE S<sup>TH</sup> DAY OF APRIL 2024, SITE NMAQFS09 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

4/8/2024 DATED: BY

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 200 BLOCK EUBANK BLVD NE NB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 9<sup>TH</sup> DAY OF APRIL 2024, SITE NMAQFS10 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 4/9/2024 BY Patrick Walters

Patrick Walters PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 700 BLOCK OF AVENIDA CESAR CHAVEZ EB

# SYSTEM TEST ČERTIFICATE

THIS IS TO CERTIFY THAT ON THE S<sup>TH</sup> DAY OF APRIL 2024, SITE NMAQFS11 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 4/8/2024 BY Patrick Walters

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 200 BLOCK OF LOMAS BLVD NW EB

#### SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 12TH DAY OF MAY, 2023 SITE NMAQFS12 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 5/12/2023

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 300 BLOCK OF 98<sup>th</sup> ST SW NB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 6<sup>TH</sup> DAY OF MARCH, 2024 SITE NMAQFS13 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 03/06/2024 BY Patrick Walters

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 7800 BLOCK OF MONTGOMERY BLVD NE WB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 6<sup>TH</sup> DAY OF MARCH, 2024 SITE NMAQFS14 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 03/06/2024

BY Patrick Walters

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 7400 BLOCK OF MONTGOMERY BLVD NE EB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 6<sup>th</sup> day of march, 2024 site nmaqfs15 has been tested and certified. All tests and services recommended by the manufacturer have been performed. A visual test was also conducted and deemed to be satisfactory.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

BY Patrick Walters DATED: 03/06/2024

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 1500 BLOCK ELLISON DR NW EB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 9<sup>th</sup> DAY OF APRIL 2024, SITE NMAQFS16 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

> 4/9/2024 DATED: BY

TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 5900 BLK WYOMING BLVD NE NB

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 23RD DAY OF MAY, 2023 SITE NMAQFS17 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 5/23/2023

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 10111 COORS BLVD BYPASS NW S/B

#### SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 22ND DAY OF SEPTEMBER, 2023 SITE NMAQFS18 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 9/22/23

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 6550 COORS BLVD NW N/B

# SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 15TH DAY OF SEPTEMBER, 2023 SITE NMAQFS19 HAS BEEN TESTED AND CERTIFIED. ALL TESTS AND SERVICES RECOMMENDED BY THE MANUFACTURER HAVE BEEN PERFORMED. A VISUAL TEST WAS ALSO CONDUCTED AND DEEMED TO BE SATISFACTORY.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 9/15/23

PATRICK WALTERS TECHNICIAN







SIS-TRA, LLC

SYSTEM: D-ARMOR

LOCATION: 6900 BLOCK OF NM-423 NE WB

#### SYSTEM TEST CERTIFICATE

THIS IS TO CERTIFY THAT ON THE 5<sup>th</sup> day of december, 2023 site nmaqfs20 has been tested and certified. All tests and services recommended by the manufacturer have been performed. A visual test was also conducted and deemed to be satisfactory.

I, THE UNDERSIGNED, CERTIFY THAT I HAVE CONDUCTED THE ABOVE TESTS AND FOUND THE ABOVE LISTED EQUIPMENT TO BE ACCURATE.

DATED: 12/5/2023

BY

JAMES HENDRICK TECHNICIAN