


1702 weld missed the mark.



1702 poor welds




1702 Poor and rusting welds



1702 cracking exterior




1702 - Hvac ducts leaking. ~~1702~~



1702- line rubbing



1702. torn Bellon



1702- peeling finish








1702 - loose clamps


1702



1702 The weld missed the mark. Left center




1702- loose ground



1702 - exposed terminal




1702 - line rubbing



1702 - little foot space



1702. partially blocked emergency exits







1702 cracking interior.

1702 - loose wheelchain restraint pucks



1702 Poor and incomplete welds, rear of joint



1702 no weld

Right center

